







d1 mm max	1.52	1.9	2.54	2.95	3.56	4.24	4.62
d1 Dia Gauge	00	0	2	4	6	8	10
dk - max	2.51	3.22	4.11	5.36	6.6	7.85	9.12
k - max	0.86	1.24	1.75	2.18	2.6	3.05	3.48

Hammer drives are a version of self-tapping screw with multiple start threads having a large lead angle and pilot point, which are driven into pre-drilled holes with a hammer or machine press. The lack of any recess in the head effectively allows for a tamper resistant permanent assembly.

Available in various lengths & materials.

Tel: 01234 346242 www.challenge-europe.co.uk sales@challenge-europe.co.uk